

# **SURFACE AND DIRECTIONAL LIGHTS SL-29-SERIES**

#### **SPECIFICATIONS**

CONSTRUCTION: Cast aluminum or brass adjustable surface lights, easily adjustable aiming bracket; copper models

bearing a -COP suffix are constructed from extruded copper

LENS: Clear tempered glass

**SOCKET:** High temperature ceramic (GZ4) bi pin with 250°C silicone lead wires

WIRING: Black 3 foot 18/2 zip cord MOUNT: FA-111-SM surface mount FINISH: Optional finishes available

#### **ORDERING INFORMATION**


CATALOG NO. **DESCRIPTION** STANDARD FINISH

The following fixtures are equipped with 20 watt MR8 FL lamp, 20 watt maximum

SL-29 Cast aluminum mini adjustable surface light SL-29-BRS Cast brass fixture mini adjustable surface light SL-29-COP Extruded copper fixture mini adjustable surface light

Black texture Unfinished brass Unfinished copper

#### LIGHT DISTRIBUTIONS AND PHOTOMETRICS



20w MR8 FL SL-29, SL-29-BRS, SL-29-COP







JOB INFORMATION

FOCUS INDUSTRIES INC. 25301 COMMERCENTRE DRIVE

LAKE FOREST, CA 92630

Type:

Job Name:

Cat. No.:

Lamp(s):

Specifier: Contractor:



www.focusindustries.com

sales@focusindustries.com

(949) 830-1350 • FAX (949) 830-3390

Date:

### **ACCESSORIES**

#### **RECOMMENDED ENHANCEMENTS FOR SL-29 SERIES:**

FA-08-23 Round 1/8"Hex Cell Louver FA-11-23-BLUE Blue Tempered Glass Lens FA-11-23-GREEN **Green Tempered Glass Lens** FA-98-23 **Linear Spread Tempered Glass Lens** Wide Spread Tempered Glass Lens Softener For copper fixture accessories, add -C suffix to above catalog numbers

12v. fixtures: 25 foot 16/2 fixture lead wire available; add -25F to catalog number.

For use with Focus CPC or hub supplied by others.

FSA-00

Powder Coat Finishes	Black Texture (Standard)	Antique Verde	Bronze Texture	Camel	White Texture	Hunter Texture	Rust	Weathered Iron	Weathered Brown	Stucco	Rubbed Verde	Chrome Powder	Terra Cotta
Ordering Code	-BLT	-ATV	-BRT	-CAM	-WTX	-HTX	-RST	-WIR	-WBR	-STU	-RBV	-CPR	-TRC

INTER	TEK
(41	۳)
10	<b>V</b> us
• ▼∠ <sub>IST</sub>	ED GO






## **INSTALLATION INSTRUCTIONS (12V)** FOR SL-29 SURFACE AND DIRECTIONAL FIXTURES

Inspected by

- 1) Using Junction Box as a template mark holes to attach to surface. Drill hole if necessary.
  2) Bring in 12v supply wire through liquid tight connector and wire to 18/2c zip cord using blue wirenuts provided.
- 3) Attach/screw box to surface with appropriate fastner. Wire supply wire to 12v and check for proper installation.



For Questions Call 1-888-882-1350