

SL-42 Ledge Light SL-43 Rail Light

SPECIFICATIONS


FACE PLATE: Stamped brass (-BRS), Copper (-COP), Stainless Steel (-SS) or Stamped Aluminum LAMP: 5 watt G-4 bi-pin T-9 Xenon or 10 watt G-4 bi-pin T-9 Xenon. This fixture is rated 10w. MAX

LAMP LIFE: 10,000 hrs average rating **WIRING:** Black 3 foot 18/2 zip cord for 12v.


CONNECTION: FA-05 Quick Connector (not supplied) from fixture to main cable (12/2, 10/2 or 8/2 only) 12v. only


FINISH: Optional finishes available















SL-42



ORDERING INFORMATION


CATALOG NO.	DESCRIPTION	STANDARD FINISH	EST. SHIP. WEIGHT		
SL-42	Stamped aluminum Ledge light	Black texture	3.0 lbs.		
SL-42-BRS	Stamped brass Ledge light	Brass	3.0 lbs.		
SL-42-COP	Copper Ledge light	Copper	3.0 lbs.		
SL-42-SS	Stainless steel Ledge light	Stainless Steel	3.0 lbs.		
SL-43	Stamped aluminum Rail light	Black texture	3.0 lbs		
SL-43-BRS	Stamped brass Rail light	Brass	3.0 lbs		
SL-43-COP	Copper Rail light	Copper	3.0 lbs		
SL-43-SS	Stainless steel Rail light	Stainless Steel	3.0 lbs		


Note: Above lights have aluminum electrical plate. To recieve a stainless steel electrical plate replace SL with SSL when ordering. Consult factory for price.

Photometrics

FSA-00

1.00





 $\textbf{12v. fixtures:}\ 25\ \text{foot}\ 16/2\ \text{fixture lead wire available;}\ \text{add}\ \textbf{-25F}\ \text{to catalog number.}$ For use with Focus CPC or hub supplied by others.}

JOB INFORMATION	
Туре:	Date:
Job Name:	
Cat. No.:	
Lamp(s):	
Specifier:	
Contractor:	
Notes:	
FOCUS INDUSTRIES INC. 25301 COMMERCENTRE DRIVE LAKE FOREST, CA 92630	www.focusindustries.com sales@focusindustries.com (949) 830-1350 • FAX (949) 830-3390

FSA-00	TOT USC WITH	rocus cr c o	i ilab sappiic	a by others.									
Powder Coat Finishes	Black Texture (Standard)	Antique Verde	Bronze Texture	Camel	White Texture	Hunter Texture	Rust	Weathered Iron	Weathered Brown	Stucco	Rubbed Verde	Chrome Powder	Terra Cotta
Ordering Code	-BLT	-ATV	-BRT	-CAM	-WTX	-HTX	-RST	-WIR	-WBR	-STU	-RBV	-CPR	-TRC



INSTALLATION INSTRUCTONS

For SL-42 Ledge Lights **12volt**.

This fixture is rated 10w. MAX

Inspected by

Read these instructions carefully before installing this fixture.

- 1. Make sure power is turned OFF before installing or servicing this fixture.
- 2. Insert mounting plate between layers of hardscape material.
- 3. Gluing in place with cap stone is optional.
- 4. Create a channel 1/4" wide by 1/8" deep so wire is not pinched by capstone.
- 5. Route wire through break in wall to low voltage power cable.
- 5. Connect fixture wires to supply using FA-05 quick connector (optional) or other suitable means.
- 6.Turn power ON


IMPORTANT SAFETY INSTRUCTIONS TO REDUCE THE RISK OF FIRE AND INJURY TO PERSONS:

- 1) Lamp gets hot quickly; turn off/unplug/ disconnect and allow to cool down before replacing the bulb.
- 2) DO NOT touch fixture when it is operation
- 3) DO NOT look into lamp when on
- 4) Keep lamp away from materials that may burn
- 5) Use only with wattage/lamp marked on fixture warning or instructions.
- 6) Use correct light bulb base w/ corresponding socket
- 7) DO NOT operate fixture with missing/damaged cover plate.

Additional wire and connectors may be purchased directly from FOCUS INDUSTRIES.

This fixture is intended for installation in accordance with the National Electrical Code (NEC) and local code specifications. Failure to adhere to these codes and instructions may result in serious injury and /or damage to the fixture and will void the warranty. These instructions do not cover all details or variations in equipment, nor provide for every possible contingency related to installation, operation, maintenance. or mounting situation. Please call for assistance in alternate circumstances

For Questions Call 1-888-882-1350





INSTALLATION INSTRUCTONS

For SL-43 Rail Lights 12volt.

This fixture is rated 10w. MAX

Inspected by

Read these instructions carefully before installing this fixture.

- 1. Make sure power is turned OFF before installing or servicing this fixture.
- 2. Mount SL-43 in desired location with supplied screws
- 3. Route wire to low voltage power cable.
- 4. Connect fixture wires to supply using FA-05 quick connector (optional) or other suitable means.
- 5.Turn power ON

IMPORTANT SAFETY INSTRUCTIONS TO REDUCE THE RISK OF FIRE AND INJURY TO PERSONS:

- 1) Lamp gets hot quickly; turn off/unplug/ disconnect and allow to cool down before replacing the bulb.
- 2) DO NOT touch fixture when it is operation
- 3) DO NOT look into lamp when on
- 4) Keep lamp away from flammable materials
- 5) Use only with wattage/lamp marked on fixture warning or instructions.
- 6) Use correct light bulb base w/corresponding socket
- 7) DO NOT operate fixture with missing/damaged cover plate.

Additional wire and connectors may be purchased directly from FOCUS INDUSTRIES.

This fixture is intended for installation in accordance with the National Electrical Code (NEC) and local code specifications. Failure to adhere to these codes and instructions may result in serious injury and /or damage to the fixture and will void the warranty. These instructions do not cover all details or variations in equipment, nor provide for every possible contingency related to installation, operation, maintenance. or mounting situation. Please call for assistance in alternate circumstances

For Questions Call 1-888-882-1350




Illustration shown without coverplate