

For G-Type Adapter

SAVE THESE INSTRUCTIONS

Find the latch and the polarity line. Align parts as shown below and insert the adapter box into the track




Rotate the adapter box opposite the arrows until the latch snaps in place between the two track rails



Continue to depress latch until final position

Final Position



Latch snaps into place between rails

