

## **SLED™ DC INSTALLATION INSTRUCTIONS**

Thank you for buying RAB lighting fixtures. Our goal is to design the best quality products to get the job done right. We'd like to hear your comments. Call the Marketing Department at 888-RAB-1000, or email: marketing@rabweb.com






SLED Square

SLEDR Round

### **IMPORTANT**

READ CAREFULLY BEFORE INSTALLING FIXTURE. RETAIN THESE INSTRUCTIONS FOR FUTURE REFERENCE.
RAB fixtures must be wired in accordance with the National Electrical Code and all applicable local codes. Proper grounding is required for safety. THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE WITH THE APPLICABLE INSTALLATION CODE BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED.

WARNING: Make certain power is OFF before installing or maintaining fixture. No user serviceable parts inside.





# **SLED™ DC INSTALLATION INSTRUCTIONS**

#### MOUNTING


Secure the SLED steplight to any indoor or outdoor recessed or surface junction box.

- Loosen Housing Screws and remove Mounting Plate. Screws will remain in place with O-ring retaining gaskets. Fixture may hang from the tether while installing.
- Place Wall Gasket and Mounting Plate over recessed box.
- 3. Attach Mounting Plate with supplied Mounting Plate Screws.
- 4. Pull supply wires from box through mounting plate and wire fixture as shown in the wiring section.
- 5. Check **Housing Gasket**. It should remain firmly around the inside of the Housing.
- 6. Align Housing to Mounting Plate.
- 7. Make sure all gaskets are properly seated. Tighten Housing Screws.
- 8. If outdoor surface is irregular, use caulk to seal any gaps around the Mounting Plate.

#### TROUBLESHOOTING

- 1. Check that the line voltage at fixture is correct. Refer to wiring directions.
- 2. Is the fixture grounded properly?
- 3. Is the photocell is functioning properly (if used)?

### **SLED5** Cool LED Square Steplight



All results are according to IESNA LM-79-2008; Approved Method for the Electrical and Photometric Testing of Solid-State Lighting. The U.S. Department of Energy (DOE) verifies

Visit www.lightingfacts.com for the Label Reference Guide.

Registration Number: WVMA-BX5KZF

### **Easy Installation & Product Help**


#### Tech Help Line Call our experts

#### rabweb.com Visit our website for product info

### WIRING

Universal DC voltage driver permits operation at 10VDC to 30VDC.

- 1. Connect the WHITE fixture lead to the (+) supply lead.
- 2. Connect the BLACK fixture lead to the (-) supply lead.
- 3. Connect the bare copper Ground wire from fixture to supply ground.



### CLEANING & MAINTENANCE

CAUTION: Be sure fixture temperature is cool enough to touch. Do not clean or maintain while fixture is energized.

- Clean glass lens with non-abrasive glass cleaning solution.
- 2. Do not remove LED lens to clean the LED. Do not touch the LED.

Note: These instructions do not cover all details or variations in equipment nor do they provide for every possible situation during installation, operation or maintenance.

### **SLEDR5** Cool LED Round Steplight



All results are according to IESNA LM-79-2008: Approved Method for the Electrical and Photometric Testing of Solid-State Lighting. The U.S. Department of Energy (DOE) verifies product test data and results

Visit www.lightingfacts.com for the Label Reference Guide

Registration Number: WVMA-P84BYF Model Number: SLEDR5

IGHTIN